

General Notes:
The information depicted on this map represents the results of surveys made on the date indicated and can only be considered as indicating the general condition of the lake. Units otherwise noted on this map are not necessarily current or accurate.
Map depths and soundings or imbeds referred to the International Datum 1955.
TIGL 1955 and all horizontal positions are referred to North American Datum 1983.
Specific Notes refer to opposite details. To view a color version of this map, point & click the web browser to <http://www.usace.army.mil/waterways/survey/survey.htm>.
This drawing was prepared using a CAD system. Scaling may be distorted.

Drawn by: CADD
Reviewed by:
Chief, Survey Unit
Approved: — B
Date:
Clerk, NYPA Navigation and Maintenance Section

U. S. ARMY ENGINEER DISTRICT
CORPS OF ENGINEERS
BUFFALO, NEW YORK 14207-3199

SANDUSKY HARBOR, OHIO
PROJECT CONDITION SOUNDINGS 2004
SCALE: 00' FEET
50 0 100 200

Sheet reference number:
VH - 101
Sheet 1 of 4
05S-SAN-1

